



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director  
JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

May 21, 2008

Reviewed SW

<b>Mine Name:</b> Strawberry River	<b>Permit Number:</b> S0130008
<b>Operator Name:</b> Rock & Stone LLC	<b>Inspection Date:</b> May 21, 2008
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 10:00 am
<b>Other Participants:</b> Marty Appawoo	<b>Mine Status:</b> Act

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** 04-15-2010

**Purpose of Inspection:** This was a routine annual inspection

**Inspection Summary:** Mine was in full operation with several Excavators and Loaders working. Several highwall areas had unsupported overhangs that are a safety hazard. Large area south of the road was being used as a waste rock site (topsoil was stockpiled), but area was clearly outside of permitted area.

Photos were taken to document site conditions.

**Conclusions and Recommendations:** Operator has to comply with all local, state and federal rules. Operator has 10 days to file an interim bond to cover additional disturbed area (2.29 acres – \$11,900) see attached map. Operator has 90 days to file for a Large Mine Permit with DOGM. Interim bond will be adjusted after large Mine permit is completed. Failure to comply will result in a Cessation order. DOGM Assessment Officer has been notified of Inspection Report. Disturbed area south of road was photographed and GPS taken. Continue to monitor this site when in the area.

**Inspector's Signature**

LAH:pb

cc: Cliff Read- Rock & Stone

Fee

O:\WP\M013-Duchesne\S0130008-Strawberry\Draft\Insp\_StrwberryRiver\_05-21-08.doc

cc: okuniewicz.michael@dol.gov

Photos Taken 05-21-08





Mine Number: S130008

Mine Name: STRAWBERRY RIVER

Township 04.0 S Range 07.0 W Section 16

Meridian: SLBM

Inspection Date: 20/08/5/21

Map Produced by DKS

Acres Disturbed	6.09
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0.40
Total Acres Disturbed	6.49
Acres Released	0.19
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

Legend

All items symbolized in legend may not be appear on map

- Active Mines
- Inactive Mines
- Unknown Status
- County Boundary
- Interstate
- US Route
- State Route
- Primary Route
- Secondary Route
- Main Dirt Road
- Unimproved Road
- Interchange
- Trail
- Township or range line
- Section line
- Section line location doubtful
- Access
- Mine
- NonMine
- Reclaimed
- Other
- Disturbed
- Regraded
- Seeded
- Released
- Excluded
- PreExisting
- Proposed
- Bond Area
- SITLAMineral Leases
- BLM Salable Minerals
- BLM Mining Notices
- CommunityPit
- SITLAMineral Ownership

NALP Imagery date 2006



0 625 Feet

1:7,500 1 inch equals 625 feet

Verify Scale

Dept. of Natural Resources  
Division of Oil, Gas, and Mining  
Mineral Mines Program

Different data sources and input scales  
may cause misalignment of data layers.  
This product may not meet DCGM  
standards for accuracy and content.

6/4/2008 NAD 1927 UTM Zone 12N